

Vehicle details

VIN	VR3UPHPX9 R4290709	Registration date	08/11/2024	Exterior Color	Selenium Grijs
Brand	PEUGEOT	Licence Plate	1BFO158	Odometer	21 140 km
Model	208 Allure 1.2 Hybrid 100 e-DCS6	Condition of the car	Repaired after accident		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Adapter USB	✓
Spare key	✓
Remote key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres




Michelin 195/55/16 H Summer 5.0 mm

Michelin 195/55/16 H Summer 5.0 mm



Michelin 195/55/16 H Summer 6.0 mm

Michelin 195/55/16 H Summer 6.0 mm

Exterior

1		Part	Door sill	3		Part	Wing
		Position	Front left			Position	Front left
		Damages	Dented			Damages	Dented
		Comments	-			Comments	-

DEKRA Automotive Solutions

4		<table border="1"> <tr><td>Part</td><td>Exterior door mirror shell</td></tr> <tr><td>Position</td><td>Left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Exterior door mirror shell	Position	Left	Damages	Scratched	Comments	-	5		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Comments	-
Part	Exterior door mirror shell																				
Position	Left																				
Damages	Scratched																				
Comments	-																				
Part	Bumper																				
Position	Back																				
Damages	Scratched																				
Comments	-																				
6		<table border="1"> <tr><td>Part</td><td>Bumper extension moulding</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>RET</td></tr> </table>	Part	Bumper extension moulding	Position	Back	Damages	Scratched	Comments	RET	7		<table border="1"> <tr><td>Part</td><td>Special rim 16"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 16"	Position	Front right	Damages	Scratched	Comments	-
Part	Bumper extension moulding																				
Position	Back																				
Damages	Scratched																				
Comments	RET																				
Part	Special rim 16"																				
Position	Front right																				
Damages	Scratched																				
Comments	-																				
8		<table border="1"> <tr><td>Part</td><td>Safety hinch bonnet</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Safety hinch bonnet	Position	Front	Damages	Broken	Comments	-	9		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Improper repair</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Front	Damages	Improper repair	Comments	-
Part	Safety hinch bonnet																				
Position	Front																				
Damages	Broken																				
Comments	-																				
Part	Bumper																				
Position	Front																				
Damages	Improper repair																				
Comments	-																				
10		<table border="1"> <tr><td>Part</td><td>Agrafe de béquille de capot</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Agrafe de béquille de capot	Position	Front left	Damages	Missing	Comments	-	11		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>S.R.</td></tr> </table>	Part	Wing	Position	Back left	Damages	Dented	Comments	S.R.
Part	Agrafe de béquille de capot																				
Position	Front left																				
Damages	Missing																				
Comments	-																				
Part	Wing																				
Position	Back left																				
Damages	Dented																				
Comments	S.R.																				

Others

2		<table border="1"> <tr><td>Part</td><td>Support de caméra</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Support de caméra	Position	-	Damages	Scratched	Comments	-
Part	Support de caméra									
Position	-									
Damages	Scratched									
Comments	-									

Comments

Réparation Stellantis Grimbergen