

Vehicle details

VIN	VR1JCYHZ9 SY533635	Registration date	10/04/2025	Exterior Color	Noir Perla Nera
Brand	DS	Licence Plate		Odometer	25 490 km
Model	DS 7 BLUEHDI 130 AUTOMATIC PALLAS	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Spare wheel kit	✓
Rear parcel shelf	✗

Technical Document

Tyres







Michelin 235/50/19 V Summer 5.0 mm

Michelin 235/50/19 V Summer 5.0 mm











Michelin 235/50/19 V Summer 5.0 mm

Michelin 235/50/19 V Summer 5.0 mm


Exterior

2		Part	Special rim 19"	3		Part	Special rim 19"
		Position	Front left			Position	Back left
4		Damages	Chemical deposit	5		Damages	Chemical deposit
		Comments	-			Comments	-
		Part	Special rim 19"			Part	Special rim 19"
		Position	Back right			Position	Front right
		Damages	Chemical deposit			Damages	Scratched
		Comments	-			Comments	-

DEKRA Automotive Solutions

6		<table border="1"> <tr><td>Part</td><td>Exterior door mirror shell</td></tr> <tr><td>Position</td><td>Right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Exterior door mirror shell	Position	Right	Damages	Scratched	Comments	-	7		<table border="1"> <tr><td>Part</td><td>Tailgate spoiler</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Comments</td><td>ovb</td></tr> </table>	Part	Tailgate spoiler	Position	Back	Damages	Chemical deposit	Comments	ovb
Part	Exterior door mirror shell																				
Position	Right																				
Damages	Scratched																				
Comments	-																				
Part	Tailgate spoiler																				
Position	Back																				
Damages	Chemical deposit																				
Comments	ovb																				
8		<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Comments</td><td>ovb</td></tr> </table>	Part	Bonnet	Position	Front	Damages	Chemical deposit	Comments	ovb	9		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Comments	-
Part	Bonnet																				
Position	Front																				
Damages	Chemical deposit																				
Comments	ovb																				
Part	Bumper																				
Position	Back																				
Damages	Scratched																				
Comments	-																				
10		<table border="1"> <tr><td>Part</td><td>Tailgate / Boot door</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Tailgate / Boot door	Position	Back	Damages	Scratched	Comments	-	11		<table border="1"> <tr><td>Part</td><td>Tailgate / Boot door badge</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Not conform</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Tailgate / Boot door badge	Position	-	Damages	Not conform	Comments	-
Part	Tailgate / Boot door																				
Position	Back																				
Damages	Scratched																				
Comments	-																				
Part	Tailgate / Boot door badge																				
Position	-																				
Damages	Not conform																				
Comments	-																				
12		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wing	Position	Back right	Damages	Dented	Comments	-	13		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>2x</td></tr> </table>	Part	Door	Position	Front right	Damages	Dented	Comments	2x
Part	Wing																				
Position	Back right																				
Damages	Dented																				
Comments	-																				
Part	Door																				
Position	Front right																				
Damages	Dented																				
Comments	2x																				
14		<table border="1"> <tr><td>Part</td><td>Exterior door handles</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Exterior door handles	Position	Front right	Damages	Scratched	Comments	-	15		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wing	Position	Front right	Damages	Chemical deposit	Comments	-
Part	Exterior door handles																				
Position	Front right																				
Damages	Scratched																				
Comments	-																				
Part	Wing																				
Position	Front right																				
Damages	Chemical deposit																				
Comments	-																				

Interior damage

1		<table border="1"> <tr><td>Part</td><td>Rear parcel shelf</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Rear parcel shelf	Position	-	Damages	Missing	Comments	-
Part	Rear parcel shelf									
Position	-									
Damages	Missing									
Comments	-									