

Vehicle details

VIN	VR3USHPY8 SJ651880	Registration date	08/05/2025	Exterior Color	Perla Nera Zwart
Brand	PEUGEOT	Licence Plate		Odometer	21 923 km
Model	2008 GT Hybrid 145ch e-DSC6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Emergency compressor kit	✓
Refill emergency kit	✓

Technical Document

Tyres







Goodyear 215/60/17 H All seasons 6.0 mm

Goodyear 215/60/17 H All seasons 6.0 mm




Goodyear 215/60/17 H All seasons 7.0 mm

Goodyear 215/60/17 H All seasons 7.0 mm



Exterior

2		Part	Unpainted bumper	4		Part	Special rim 17"
		Position	Back			Position	Front left
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-
5		Part	Door	6		Part	Roof wind deflector
		Position	Back left			Position	-
		Damages	Improper repair			Damages	Chemical deposit
		Comments	stof			Comments	-

DEKRA Automotive Solutions

7		<table border="1"> <tr><td>Part</td><td>Special rim 17"</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 17"	Position	Back right	Damages	Scratched	Comments	-	8		<table border="1"> <tr><td>Part</td><td>Special rim 17"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 17"	Position	Front right	Damages	Scratched	Comments	-
Part	Special rim 17"																				
Position	Back right																				
Damages	Scratched																				
Comments	-																				
Part	Special rim 17"																				
Position	Front right																				
Damages	Scratched																				
Comments	-																				
9		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scratched	Comments	-											
Part	Bumper																				
Position	Front																				
Damages	Scratched																				
Comments	-																				

Interior damage

1		<table border="1"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Interior tailgate lining	Position	-	Damages	Scratched	Comments	-			
Part	Interior tailgate lining												
Position	-												
Damages	Scratched												
Comments	-												
3		<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Not carried out</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Interior cleaning	Position	-	Damages	Not carried out	Comments	-			
Part	Interior cleaning												
Position	-												
Damages	Not carried out												
Comments	-												