

### Vehicle details

VIN	VR1FRHPY1 S1015573	Registration date	17/04/2025	Exterior Color	Noir Perla Nera
Brand	DS	Licence Plate	2GWC921	Odometer	32 781 km
Model	DS 4 ETOILE CUIR NAPPA HYBRID	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

### Inspection Details


Inspection loc. PCD - Hödlmayr Saint-Trond



### Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

### Technical Document



### Tyres

Michelin 205/55/19 V Summer 5.0 mm







Michelin 205/55/19 V Summer 5.0 mm





Michelin 205/55/19 V Summer 5.0 mm

Michelin 205/55/19 V Summer 5.0 mm


### Exterior

2		<table border="1"> <tr><td>Part</td><td>Exterior complete</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Hail damaged</td></tr> <tr><td>Comments</td><td>Motorkap x4/ Dak x 33/ Dakstijl L x5 / Dakstijl R x2</td></tr> </table>	Part	Exterior complete	Position	-	Damages	Hail damaged	Comments	Motorkap x4/ Dak x 33/ Dakstijl L x5 / Dakstijl R x2	3		<table border="1"> <tr><td>Part</td><td>Exterior door mirror shell</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Exterior door mirror shell	Position	Front left	Damages	Scratched	Comments	-
	Part	Exterior complete																			
Position	-																				
Damages	Hail damaged																				
Comments	Motorkap x4/ Dak x 33/ Dakstijl L x5 / Dakstijl R x2																				
Part	Exterior door mirror shell																				
Position	Front left																				
Damages	Scratched																				
Comments	-																				
4		<table border="1"> <tr><td>Part</td><td>Special rim 19"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 19"	Position	Front right	Damages	Scratched	Comments	-	5		<table border="1"> <tr><td>Part</td><td>Special rim 19"</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 19"	Position	Back right	Damages	Scratched	Comments	-
Part	Special rim 19"																				
Position	Front right																				
Damages	Scratched																				
Comments	-																				
Part	Special rim 19"																				
Position	Back right																				
Damages	Scratched																				
Comments	-																				

DEKRA Automotive Solutions

6		Part	Wing	7		Part	Door
		Position	Back right			Position	Back right
		Damages	Dented			Damages	Scratched
		Comments	-			Comments	-
8		Part	Bumper	9		Part	Special rim 19"
		Position	Back			Position	Front left
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-

Interior damage

1		Part	Carpet
		Position	-
		Damages	Burnt
		Comments	-

Comments

Parc stockage : OV - Hödlmayr Saint-Trond