


Vehicle details

VIN	VR3KAHPY1 SS068135	Registration date	25/04/2025	Exterior Color	Gris Artense
Brand	PEUGEOT	Licence Plate	2GWW196	Odometer	28 011 km
Model	New 3008 GT Hybrid 145 e-DCS6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Rear parcel shelf	✓
Spare wheel kit	✗

Technical Document

Tyres







Michelin 225/55/19 V Summer 6.0 mm

Michelin 225/55/19 V Summer 6.0 mm








Michelin 225/55/19 V Summer 6.0 mm

Michelin 225/55/19 V Summer 6.0 mm


Exterior

2		Part	Special rim 19"	3		Part	Bonnet
		Position	Front left			Position	Front
		Damages	Scratched			Damages	Chemical deposit
		Comments	-			Comments	-
4		Part	Bumper	5		Part	Special rim 19"
		Position	Front			Position	Front right
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-

DEKRA Automotive Solutions

<p>6</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Special rim 19"</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 19"	Position	Back right	Damages	Scratched	Comments	-	<p>7</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper moulding</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper moulding	Position	Back	Damages	Dented	Comments	-
Part	Special rim 19"																		
Position	Back right																		
Damages	Scratched																		
Comments	-																		
Part	Bumper moulding																		
Position	Back																		
Damages	Dented																		
Comments	-																		
<p>8</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Spare wheel kit</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Spare wheel kit	Position	-	Damages	Missing	Comments	-	<p>9</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Unpainted bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Unpainted bumper	Position	Back	Damages	Scratched	Comments	-
Part	Spare wheel kit																		
Position	-																		
Damages	Missing																		
Comments	-																		
Part	Unpainted bumper																		
Position	Back																		
Damages	Scratched																		
Comments	-																		
<p>10</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Roof wind deflector</td></tr> <tr><td>Position</td><td>Right</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Roof wind deflector	Position	Right	Damages	Stained/dirty	Comments	-	<p>11</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door sill</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Door sill	Position	Back right	Damages	Scratched	Comments	-
Part	Roof wind deflector																		
Position	Right																		
Damages	Stained/dirty																		
Comments	-																		
Part	Door sill																		
Position	Back right																		
Damages	Scratched																		
Comments	-																		
<p>12</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>Centre</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Roof	Position	Centre	Damages	Chemical deposit	Comments	-										
Part	Roof																		
Position	Centre																		
Damages	Chemical deposit																		
Comments	-																		

Interior damage

<p>1</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Fabric seat</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Burnt</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Fabric seat	Position	-	Damages	Burnt	Comments	-		
Part	Fabric seat										
Position	-										
Damages	Burnt										
Comments	-										

Comments

Parc stockage : FCA - Hödlmayr Saint-Trond