

Vehicle details

VIN	VR3USHPYX SJ646714	Registration date	08/05/2025	Exterior Color	Selenium Grijs
Brand	PEUGEOT	Licence Plate		Odometer	22 419 km
Model	2008 GT Hybrid 145ch e-DSC6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Spare wheel kit ✓

Technical Document

Tyres







Goodyear 215/60/17 H All seasons 5.0 mm

Goodyear 215/60/17 H All seasons 5.0 mm






Goodyear 215/60/17 H All seasons 5.0 mm

Goodyear 215/60/17 H All seasons 5.0 mm

Exterior

1		Part	Tyre	2		Part	Tyre
		Position	Front right			Position	Front left
3		Damages	Not conform	4		Damages	Not conform
		Comments	draairichting verkeerd			Comments	draairichting verkeerd
		Part	Exterior door mirror shell			Part	Wing
		Position	Right			Position	Front left
		Damages	Scratched			Damages	Improper repair
		Comments	-			Comments	overspray

DEKRA Automotive Solutions

<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper moulding</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper moulding	Position	Front right	Damages	Broken	Comments	-	<p>6</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Unpainted bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Unpainted bumper	Position	Front	Damages	Scratched	Comments	-
Part	Bumper moulding																		
Position	Front right																		
Damages	Broken																		
Comments	-																		
Part	Unpainted bumper																		
Position	Front																		
Damages	Scratched																		
Comments	-																		
<p>7</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Back right	Damages	Scratched	Comments	-	<p>8</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wing	Position	Back right	Damages	Scratched	Comments	-
Part	Bumper																		
Position	Back right																		
Damages	Scratched																		
Comments	-																		
Part	Wing																		
Position	Back right																		
Damages	Scratched																		
Comments	-																		
<p>9</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Wing extension moulding</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wing extension moulding	Position	Back right	Damages	Scratched	Comments	-										
Part	Wing extension moulding																		
Position	Back right																		
Damages	Scratched																		
Comments	-																		