

Vehicle details

VIN	VR7CCHPV3 ST054802	Registration date	05/05/2025	Exterior Color	Mercury Grey (metall)
Brand	CITROEN	Licence Plate		Odometer	25 755 km
Model	New C3 Turbo 100 ch Manual MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element





Rear parcel shelf	✓
Spare wheel kit	✗

Technical Document





Tyres




Exterior

1		Part	Special rim 17"	2		Part	Exterior door mirror shell
		Position	Front right			Position	Front right
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-
3		Part	Door sill	4		Part	Door panel
		Position	Front right			Position	Back right
		Damages	Dented			Damages	Dented
		Comments	-			Comments	-

DEKRA Automotive Solutions

<p>6</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Special rim 17"</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 17"	Position	Back right	Damages	Scratched	Comments	-	<p>7</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Back right	Damages	Scratched	Comments	-
Part	Special rim 17"																		
Position	Back right																		
Damages	Scratched																		
Comments	-																		
Part	Bumper																		
Position	Back right																		
Damages	Scratched																		
Comments	-																		
<p>8</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bonnet	Position	Front	Damages	Chemical deposit	Comments	-	<p>9</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Spare wheel kit</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Spare wheel kit	Position	-	Damages	Missing	Comments	-
Part	Bonnet																		
Position	Front																		
Damages	Chemical deposit																		
Comments	-																		
Part	Spare wheel kit																		
Position	-																		
Damages	Missing																		
Comments	-																		

Interior damage

<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior roof lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Interior roof lining	Position	-	Damages	Stained/dirty	Comments	-
Part	Interior roof lining								
Position	-								
Damages	Stained/dirty								
Comments	-								

Comments

Parc stockage : FCA - Hödlmayr Saint-Trond