


Vehicle details

VIN	VR1FRHPY3 S1012853	Registration date	07/04/2025	Exterior Color	Gris Platinum
Brand	DS	Licence Plate	N/A	Odometer	45 447 km
Model	DS 4 ETOILE ALCANTARA@ HYBRID	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Spare wheel kit	✓
Rear parcel shelf	✓





Technical Document

Tyres







Nexen 205/55/19 V Summer 6.0 mm
 Michelin 205/55/19 V Summer 4.0 mm
 Nexen 205/55/19 V Summer 6.0 mm
 Michelin 205/55/19 V Summer 4.0 mm


Exterior

1		Part	Special rim 19"	2		Part	Engine soundproofing
		Position	Front left			Position	-
		Damages	Scratched			Damages	Cut
		Comments	-			Comments	-
3		Part	Bumper moulding	4		Part	Bumper
		Position	Front			Position	Front right
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-

DEKRA Automotive Solutions

<p>5</p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Special rim 19"</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 19"	Position	Back right	Damages	Scratched	Comments	-	<p>7</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Windscreen</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Windscreen	Position	Front	Damages	Broken	Comments	-
Part	Special rim 19"																		
Position	Back right																		
Damages	Scratched																		
Comments	-																		
Part	Windscreen																		
Position	Front																		
Damages	Broken																		
Comments	-																		
<p>8</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Front left	Damages	Scratched	Comments	-	<p>9</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>ovb</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Comments	ovb
Part	Bumper																		
Position	Front left																		
Damages	Scratched																		
Comments	-																		
Part	Bumper																		
Position	Back																		
Damages	Scratched																		
Comments	ovb																		

Interior damage

<p>6</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Interior tailgate lining	Position	-	Damages	Scratched	Comments	-
Part	Interior tailgate lining								
Position	-								
Damages	Scratched								
Comments	-								

Comments

Parc stockage : FCA - Hödlmayr Saint-Trond