


Vehicle details

VIN	VR3KAHPY3 SS068119	Registration date	24/04/2025	Exterior Color	Gris Artense
Brand	PEUGEOT	Licence Plate		Odometer	20 029 km
Model	New 3008 GT Hybrid 145 e-DCS6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details


Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Refill emergency kit	✓
Rear parcel shelf	✓
Emergency compressor kit	✗

Technical Document



Tyres







Front left: Michelin 225/55/19 V Summer 6.0 mm

Front right: Michelin 225/55/19 V Summer 6.0 mm





Rear left: Michelin 225/55/19 V Summer 7.0 mm

Rear right: Michelin 225/55/19 V Summer 7.0 mm

Exterior

1		Part: Special rim 19"	2		Part: Bumper
	Position: Front left	Damages: Scratched		Position: Front	Damages: Scratched
3		Part: Tailgate / Boot door	4		Part: Bumper
	Position: Back	Damages: Stone impact		Position: Back left	Damages: Scratched

DEKRA Automotive Solutions

<p>5</p>		<table border="1"> <tr><td>Part</td><td>Emergency compressor kit</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Emergency compressor kit	Position	-	Damages	Missing	Comments	-	<p>6</p>		<table border="1"> <tr><td>Part</td><td>Door sill</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Door sill	Position	Back left	Damages	Dented	Comments	-
Part	Emergency compressor kit																				
Position	-																				
Damages	Missing																				
Comments	-																				
Part	Door sill																				
Position	Back left																				
Damages	Dented																				
Comments	-																				
<p>7</p>		<table border="1"> <tr><td>Part</td><td>Unpainted bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Unpainted bumper	Position	Back	Damages	Scratched	Comments	-	<p>8</p>		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wing	Position	Front right	Damages	Dented	Comments	-
Part	Unpainted bumper																				
Position	Back																				
Damages	Scratched																				
Comments	-																				
Part	Wing																				
Position	Front right																				
Damages	Dented																				
Comments	-																				

Comments

Parc stockage : OV - Hödlmayr Saint-Trond