

DEKRA Automotive Solutions

Vehicle details

VIN	VR1URHPY0 SW031564	Registration date	19/05/2025	Exterior Color	Rouge Diva
Brand	DS	Licence Plate		Odometer	12 122 km
Model	DS 3 ETOILE HYBRID	Condition of the car	Unknown	Pre-damage	Unknown
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond
-----------------	----------------------------




Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

--

Tyres











Goodyear 215/55/18 V Summer 7.0 mm

Goodyear 215/55/18 V Summer 7.0 mm






Goodyear 215/55/18 V Summer 7.0 mm

Goodyear 215/55/18 V Summer 7.0 mm


Exterior

2		Part	Special rim 18"	3		Part	Special rim 18"
		Position	Front left			Position	Front right
4		Damages	Scratched	5		Damages	Scratched
		Comments	-			Comments	-
4		Part	Special rim 18"	5		Position	Wing extension moulding
		Position	Back right			Position	Back right
5		Damages	Scratched	5		Damages	Scratched
		Comments	-			Comments	-

DEKRA Automotive Solutions

6		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Back	Damages	Dented	Comments	-	7		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Door	Position	Back left	Damages	Dented	Comments	-
Part	Bumper																				
Position	Back																				
Damages	Dented																				
Comments	-																				
Part	Door																				
Position	Back left																				
Damages	Dented																				
Comments	-																				
8		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wing	Position	Back right	Damages	Dented	Comments	-	9		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>x2</td></tr> </table>	Part	Door	Position	Back right	Damages	Dented	Comments	x2
Part	Wing																				
Position	Back right																				
Damages	Dented																				
Comments	-																				
Part	Door																				
Position	Back right																				
Damages	Dented																				
Comments	x2																				
10		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Improper repair</td></tr> <tr><td>Comments</td><td>kleurverschil</td></tr> </table>	Part	Bumper	Position	Front	Damages	Improper repair	Comments	kleurverschil											
Part	Bumper																				
Position	Front																				
Damages	Improper repair																				
Comments	kleurverschil																				

Others

1		<table border="1"> <tr><td>Part</td><td>Fuel lumpsum</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Fuel lumpsum	Position	-	Damages	Missing	Comments	-			
Part	Fuel lumpsum												
Position	-												
Damages	Missing												
Comments	-												

Comments

Parc stockage : FCA - Hödlmayr Saint-Trond