

Vehicle details

VIN	VR7ARHPY5 SL017069	Registration date	15/04/2025	Exterior Color	Okenite White
Brand	CITROEN	Licence Plate	N/A	Odometer	16 760 km
Model	C5 Aircross Hybrid 145 ch Automatic MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Triangle	✓
Safety vest	✓
Rear parcel shelf	✓
Fire extinguisher	✓
Floor mat BR	✗
Floor mat BL	✗
Floor mat FR	✗
Floor mat FL	✗



Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
First aid kit	✓




Tyres



Exterior

6		Part	Bumper	7		Part	Lower bumper
		Position	Back			Position	Back
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-

DEKRA Automotive Solutions

<p>8</p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing moulding</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wing moulding	Position	Front left	Damages	Scratched	Comments	-	<p>9</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper moulding</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper moulding	Position	Front	Damages	Scratched	Comments	-
Part	Wing moulding																		
Position	Front left																		
Damages	Scratched																		
Comments	-																		
Part	Bumper moulding																		
Position	Front																		
Damages	Scratched																		
Comments	-																		
<p>10</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Bumper grille</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Misaligned</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper grille	Position	Front	Damages	Misaligned	Comments	-										
Part	Bumper grille																		
Position	Front																		
Damages	Misaligned																		
Comments	-																		

Interior damage

<p>1</p> 	<table border="1"> <tr><td>Part</td><td>Floor mat</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Floor mat	Position	Back right	Damages	Missing	Comments	-										
Part	Floor mat																		
Position	Back right																		
Damages	Missing																		
Comments	-																		
<p>2</p> 	<table border="1"> <tr><td>Part</td><td>Floor mat</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Floor mat	Position	Back left	Damages	Missing	Comments	-	<p>3</p> 	<table border="1"> <tr><td>Part</td><td>Floor mat</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Floor mat	Position	Front right	Damages	Missing	Comments	-
Part	Floor mat																		
Position	Back left																		
Damages	Missing																		
Comments	-																		
Part	Floor mat																		
Position	Front right																		
Damages	Missing																		
Comments	-																		
<p>4</p> 	<table border="1"> <tr><td>Part</td><td>Floor mat</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Floor mat	Position	Front left	Damages	Missing	Comments	-	<p>5</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Instrument cluster</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Instrument cluster	Position	-	Damages	Broken	Comments	-
Part	Floor mat																		
Position	Front left																		
Damages	Missing																		
Comments	-																		
Part	Instrument cluster																		
Position	-																		
Damages	Broken																		
Comments	-																		

Comments

kmstand niet afleesbaar op dashboard  
 Parc stockage : OV - Hödlmayr Saint-Trond