


DEKRA Automotive Solutions

Vehicle details

VIN	VR7BAHPY6 SE027447	Registration date	23/05/2025	Exterior Color	Mercury Grey
Brand	CITROEN	Licence Plate		Odometer	11 203 km
Model	New C4 Hybrid 145 ch Automatic MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit	✗
Refill emergency kit	✗
Rear parcel shelf	✗

Technical Document

Spare key	✓
Key	✓

Tyres







Goodyear 195/60/18 H Summer 6.0 mm

Goodyear 195/60/18 H Summer 6.0 mm

Goodyear 195/60/18 H Summer 7.0 mm



Goodyear 195/60/18 H Summer 7.0 mm

Exterior

 <p>3</p>	<table border="1"> <tr><td>Part</td><td>Emergency compressor kit</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Emergency compressor kit	Position	-	Damages	Missing	Comments	-	 <p>4</p>	<table border="1"> <tr><td>Part</td><td>Refill emergency kit</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Refill emergency kit	Position	-	Damages	Missing	Comments	-
	Part	Emergency compressor kit																	
	Position	-																	
Damages	Missing																		
Comments	-																		
Part	Refill emergency kit																		
Position	-																		
Damages	Missing																		
Comments	-																		
 <p>5</p>	<table border="1"> <tr><td>Part</td><td>Rear door strip</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Rear door strip	Position	-	Damages	Stone impact	Comments	-	 <p>6</p>	<table border="1"> <tr><td>Part</td><td>Special rim 18"</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 18"	Position	Front left	Damages	Scratched	Comments	-
	Part	Rear door strip																	
	Position	-																	
Damages	Stone impact																		
Comments	-																		
Part	Special rim 18"																		
Position	Front left																		
Damages	Scratched																		
Comments	-																		

Interior damage

DEKRA Automotive Solutions

1 	Part	Rear parcel shelf
	Position	-
	Damages	Missing
	Comments	-
2 	Part	Adjustable Boot Space
	Position	-
	Damages	Missing
	Comments	-