DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VR1J45GBU PY677461	Registration date	17/01/2025	Exterior Color	B0MM0B B0NKKJ GRIS T
Brand	DS	Licence Plate		Odometer	11 083 km
Model	DS 7 E-TENSE 360 RIVOLI	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Parc LLD

Removable element

Emergency compressor kit	✔
Refill emergency kit	✔
In-car tools	✔
Toolkit	✔
Rear parcel shelf	✔
Floor mat BR	✔
Floor mat BL	✔
Floor mat FR	✔
Floor mat FL	✔
Towing hook	✔

Technical Document

Service manual holder	✔
User manual	✔
Warranty booklet	✔
Adapter USB	✔
Spare key	✔
Card Key	✔
Certificate of conformity	✔
Title / License document	✔

Tyres

Michelin 245/35/21 Y Summer 6.0 mm

Michelin 245/35/21 Y Summer 7.0 mm



Michelin 245/35/21 Y Summer 6.0 mm

Michelin 245/35/21 Y Summer 7.0 mm

Exterior

1



Part	Special rim 21"
Position	Front left
Damages	Scratched
Comments	-

2

Part	Special rim 21"
Position	Back left
Damages	Scratched
Comments	-

DEKRA

DEKRA Automotive Solutions

Appraisal Report

3

Part	Door
Position	-
Damages	Not carried out
Comments	-

4

Part	Exterior complete
Position	-
Damages	Not conform
Comments	Trempée, neige retirée par moi-même et très sale...

5

Part	Special rim 21"
Position	Back right
Damages	Scratched
Comments	-

6

Part	Special rim 21"
Position	Front right
Damages	Scratched
Comments	-

7

Part	Tyre
Position	Front right
Damages	Cut
Comments	-

8

Part	Bumper
Position	Front
Damages	Scratched
Comments	0€

9

Part	Bumper moulding
Position	Front right
Damages	Scratched
Comments	-

10

Part	Roof post A/B/C
Position	Back left
Damages	Stained/dirty
Comments	Stickers usine...

11

Part	Door
Position	Back left
Damages	Dented
Comments	-

12

Part	Bumper
Position	Back
Damages	Scratched
Comments	-

13

Part	Rear light (bumper)
Position	Back left
Damages	Scratched
Comments	-

14

Part	Unpainted bumper
Position	Back
Damages	Dented
Comments	-

15

Part	Roof post A/B/C
Position	Back right
Damages	Stained/dirty
Comments	Stickers usine...

16

Part	Roof
Position	-
Damages	Chemical deposit
Comments	S.R.

17

Part	Door jamb trim
Position	Front left
Damages	Scratched
Comments	-

18

Part	Door jamb trim
Position	Back left
Damages	Scratched
Comments	-

DEKRA Automotive Solutions

19		Part	Wing	20		Part	Door
		Position	Front right			Position	Front right
		Damages	Dented			Damages	Dented
		Comments	-			Comments	-

Comments

Sans conducteur