DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VR1J45GBU PY675536	Registration date	05/03/2025	Exterior Color	Gris Laqu
Brand	DS	Licence Plate	00xx00	Odometer	8 448 km
Model	DS 7 E-TENSE 360 PERFORMANCE LINE+	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond		

Removable element

Emergency compressor kit	✔
Refill emergency kit	✔
Triangle	✔
Safety vest	✔
Rear parcel shelf	✔
Floor mat BR	✔
Floor mat BL	✔
Floor mat FR	✔
Floor mat FL	✔
Fire extinguisher	✔
Vehicle charger	✔

Technical Document

Service manual holder	✔
User manual	✔
First aid kit	✔

Tyres

Michelin 245/35/21 V Summer 6.0 mm

Michelin 245/35/21 V Summer 6.0 mm



Michelin 245/35/21 V Summer 7.0 mm

Michelin 245/35/21 V Summer 7.0 mm

Exterior

DEKRA Automotive Solutions

2

Part	Special rim 21"
Position	Back right
Damages	Scratched
Comments	-

3

Part	Special rim 21"
Position	Front right
Damages	Scratched
Comments	-

Interior damage

1

Part	Interior tailgate lining
Position	-
Damages	Scratched
Comments	-

Others

4

Part	Service
Position	-
Damages	Missing
Comments	-