


Vehicle details

VIN	VR1JCYHZ7 RY586022	Registration date	28/01/2025	Exterior Color	Perla Nera Zwart
Brand	DS	Licence Plate	N/A	Odometer	11 719 km
Model	DS 7 BLUEHDI 130 AUTOMATIC OPERA	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Rear parcel shelf	✓
Spare wheel kit	✗

Technical Document

Tyres



Exterior

1		Part	Spare wheel kit	2		Part	Rear window tinted
		Position	-			Position	-
		Damages	Missing			Damages	Sticker marked
		Comments	-			Comments	-
3		Part	Bumper				
		Position	Back				
		Damages	Dented				
		Comments	-				