

Vehicle details

VIN	VR1JCYHZ0 SY532714	Registration date	10/04/2025	Exterior Color	Vol de Nuit
Brand	DS	Licence Plate		Odometer	22 828 km
Model	DS 7 BLUEHDI 130 AUTOMATIC PALLAS	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Emergency compressor kit	✓
Refill emergency kit	✗


Technical Document

Service manual holder	✓
User manual	✓

Tyres



Exterior

1		Part	Refill emergency kit	2		Part	Exterior door mirror shell
		Position	-			Position	Right
3		Damages	Missing leeg	4		Damages	Scratched
		Comments	-			Comments	-
		Part	Tailgate / Boot door			Part	Door
		Position	-			Position	Back right
		Damages	Stone impact			Damages	Dented
		Comments	-			Comments	-

DEKRA Automotive Solutions

<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Door	Position	Front right	Damages	Scratched	Comments	-	<p>6</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Roof post A/B/C</td></tr> <tr><td>Position</td><td>Right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Roof post A/B/C	Position	Right	Damages	Scratched	Comments	-
Part	Door																		
Position	Front right																		
Damages	Scratched																		
Comments	-																		
Part	Roof post A/B/C																		
Position	Right																		
Damages	Scratched																		
Comments	-																		
<p>7</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Engine soundproofing</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Cut</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Engine soundproofing	Position	-	Damages	Cut	Comments	-	<p>9</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Front	Damages	Stone impact	Comments	-
Part	Engine soundproofing																		
Position	-																		
Damages	Cut																		
Comments	-																		
Part	Bumper																		
Position	Front																		
Damages	Stone impact																		
Comments	-																		

Interior damage

<p>8</p>  <p>● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Not carried out</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Interior cleaning	Position	-	Damages	Not carried out	Comments	-
Part	Interior cleaning								
Position	-								
Damages	Not carried out								
Comments	-								