

Vehicle details

VIN	VR1JCYHZ9 SY518861	Registration date	25/03/2025	Exterior Color	Cristal Pearl
Brand	DS	Licence Plate		Odometer	22 238 km
Model	DS 7 BLUEHDI 130 AUTOMATIC ETOILE	Condition of the car	Condition of use		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details


Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓

Technical Document



Tyres



Exterior

2		Part	Roof	3		Part	Bumper
		Position	-			Position	Front right
		Damages	Dented			Damages	Scratched
		Comments	75€ S.R.			Comments	-

DEKRA Automotive Solutions

4		Part	Special rim 19"	7		Part	Door
		Position	Back left			Position	Front right
		Damages	Chemical deposit			Damages	Dented
		Comments	-			Comments	150€
		● ●				● ●	

Interior damage

5		Part	Trappe de garniture de hayon	6		Part	Interior tailgate lining
		Position	Back			Position	-
		Damages	Dented			Damages	Scratched
		Comments	2 pièces			Comments	-
		● ● ● ●				●	

Others

1		Part	Service
		Position	-
		Damages	Missing
		Comments	200€
		●	