

Vehicle details

VIN	VR7CBZYA3 ST106840	Registration date	09/07/2025	Exterior Color	Mercury Grey (mtalli)
Brand	CITROEN	Licence Plate	2HGQ430	Odometer	7 526 km
Model	New ë-C3 Electric 113 ch Comfort Range MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Spare wheel kit	✓
Emergency compressor kit	✓
Triangle	✓
Safety vest	✓
Rear parcel shelf	✓
Fire extinguisher	✓

Technical Document

Service manual holder	✓
User manual	✓
First aid kit	✓

Tyres



Exterior

1		Part	Special rim 17"	2		Part	Exterior door mirror shell
		Position	Front left			Position	Front left
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-

DEKRA Automotive Solutions

<p>3</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Door</td> </tr> <tr> <td>Position</td> <td>Back left</td> </tr> <tr> <td>Damages</td> <td>Scratched</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </tbody> </table>	Part	Door	Position	Back left	Damages	Scratched	Comments	-	<p>4</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Wing moulding</td> </tr> <tr> <td>Position</td> <td>Back left</td> </tr> <tr> <td>Damages</td> <td>Scratched</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </tbody> </table>	Part	Wing moulding	Position	Back left	Damages	Scratched	Comments	-
Part	Door																		
Position	Back left																		
Damages	Scratched																		
Comments	-																		
Part	Wing moulding																		
Position	Back left																		
Damages	Scratched																		
Comments	-																		
<p>5</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Door entry seal</td> </tr> <tr> <td>Position</td> <td>Back right</td> </tr> <tr> <td>Damages</td> <td>Broken</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </tbody> </table>	Part	Door entry seal	Position	Back right	Damages	Broken	Comments	-	<p>6</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Tailgate / Boot door</td> </tr> <tr> <td>Position</td> <td>Back</td> </tr> <tr> <td>Damages</td> <td>Scratched</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </tbody> </table>	Part	Tailgate / Boot door	Position	Back	Damages	Scratched	Comments	-
Part	Door entry seal																		
Position	Back right																		
Damages	Broken																		
Comments	-																		
Part	Tailgate / Boot door																		
Position	Back																		
Damages	Scratched																		
Comments	-																		