

Vehicle details

VIN	VR1URHPY7 SW023591	Registration date	07/04/2025	Exterior Color	Vol de Nuit
Brand	DS	Licence Plate		Odometer	24 138 km
Model	DS 3 ETOILE HYBRID	Condition of the car	Unknown	Pre-damage	
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond
-----------------	----------------------------




Removable element

Spare wheel (wheel & tyre)	✓
----------------------------	---

Technical Document

Tyres



Goodyear 215/55/18 V Summer 5.0 mm

Goodyear 215/55/18 V Summer 5.0 mm

Goodyear 215/55/18 V Summer 6.0 mm

Goodyear 215/55/18 V Summer 6.0 mm

Exterior

2		Part	Door	3		Part	Roof
		Position	Back left			Position	-
4		Damages	Dented	5		Damages	Chemical deposit
		Comments	-			Comments	-
6		Part	Wing moulding			Part	Bumper
		Position	Front right			Position	Front right
		Damages	Stained/dirty			Damages	Scratched
		Comments	blanchi par le polish			Comments	ne part pas au lustrage,
		Part	Unpainted bumper				
		Position	Back				
		Damages	Scratched				
		Comments	-				

Others

1		Part	Service
		Position	-
		Damages	Missing
		Comments	-