

Vehicle details

VIN	VR7ARHPY1 SL017201	Registration date	15/04/2025	Exterior Color	Platinum Grey
Brand	CITROEN	Licence Plate		Odometer	22 116 km
Model	C5 Aircross Hybrid 145 ch Automatic MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Adapter USB	✓
Card Key	✓

Tyres



Michelin 225/55/18 V Summer 5.0 mm

Michelin 225/55/18 V Summer 5.0 mm

Michelin 225/55/18 V Summer 6.0 mm

Michelin 225/55/18 V Summer 6.0 mm

Exterior

1		Part	Bumper	2		Part	Spoiler
		Position	Front			Position	Front right
3		Damages	Scratched	4		Damages	Scratched
		Comments	1h			Comments	190€ S.R.
3		Part	Fog light trim	4		Part	Wing
		Position	Front right			Position	Front left
4		Damages	Damaged	4		Damages	Scratched
		Comments	-			Comments	0€

DEKRA Automotive Solutions

<p>5</p>  <p>● ● ● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Unpainted bumper</td> </tr> <tr> <td>Position</td> <td>Back</td> </tr> <tr> <td>Damages</td> <td>Scratched</td> </tr> <tr> <td>Comments</td> <td>190€ S.R.</td> </tr> </tbody> </table>	Part	Unpainted bumper	Position	Back	Damages	Scratched	Comments	190€ S.R.	<p>6</p>  <p>● ● ● ● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Door</td> </tr> <tr> <td>Position</td> <td>Back right</td> </tr> <tr> <td>Damages</td> <td>Dent & Chips</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </tbody> </table>	Part	Door	Position	Back right	Damages	Dent & Chips	Comments	-
Part	Unpainted bumper																		
Position	Back																		
Damages	Scratched																		
Comments	190€ S.R.																		
Part	Door																		
Position	Back right																		
Damages	Dent & Chips																		
Comments	-																		
<p>7</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Bonnet</td> </tr> <tr> <td>Position</td> <td>-</td> </tr> <tr> <td>Damages</td> <td>Stone impact</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </tbody> </table>	Part	Bonnet	Position	-	Damages	Stone impact	Comments	-	<p>8</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Wing extension moulding</td> </tr> <tr> <td>Position</td> <td>Back left</td> </tr> <tr> <td>Damages</td> <td>Scratched</td> </tr> <tr> <td>Comments</td> <td>Superficiel</td> </tr> </tbody> </table>	Part	Wing extension moulding	Position	Back left	Damages	Scratched	Comments	Superficiel
Part	Bonnet																		
Position	-																		
Damages	Stone impact																		
Comments	-																		
Part	Wing extension moulding																		
Position	Back left																		
Damages	Scratched																		
Comments	Superficiel																		