


DEKRA Automotive Solutions

Vehicle details

VIN	VR3UPHPX0 S4030141	Registration date	21/03/2025	Exterior Color	Gris Artense
Brand	PEUGEOT	Licence Plate	2FNT846	Odometer	14 838 km
Model	208 GT 1.2 Hybrid 110ch e-DSC6	Condition of the car	Condition of use		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Spare wheel (wheel & tyre)	✓
Spare wheel kit	✓
In-car tools	✓
Toolkit	✓
Jack	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓

Technical Document



Service manual holder	✓
User manual	✓
Warranty booklet	✓
Adapter USB	✓
Spare key	✓
Card Key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres











Michelin 205/45/17 H Summer 6.0 mm
 Michelin 205/45/17 W Summer 5.0 mm
 Michelin 205/45/17 H Summer 7.0 mm
 Michelin 205/45/17 H Summer 7.0 mm
 -/-/- Emergency spare wheel 100.0 %

Exterior

 <p>1</p>	Part	Bumper	 <p>2</p>
	Position	Back	
	Damages	Scratched	
	Comments	-	
	Part	Roof post A/B/C	
	Position	Back right	
	Damages	Scratched	
	Comments	-	

DEKRA Automotive Solutions

<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wing	Position	Back right	Damages	Dent & Chips	Comments	-	<p>4</p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Tyre</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Not conform</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Tyre	Position	Front right	Damages	Not conform	Comments	-
Part	Wing																		
Position	Back right																		
Damages	Dent & Chips																		
Comments	-																		
Part	Tyre																		
Position	Front right																		
Damages	Not conform																		
Comments	-																		
<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Windscreen with camera</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Windscreen with camera	Position	-	Damages	Stone impact	Comments	-	<p>6</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Front right	Damages	Scratched	Comments	-
Part	Windscreen with camera																		
Position	-																		
Damages	Stone impact																		
Comments	-																		
Part	Bumper																		
Position	Front right																		
Damages	Scratched																		
Comments	-																		
<p>7</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Window</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>Défaut lèche vitre</td></tr> </table>	Part	Window	Position	Back right	Damages	Scratched	Comments	Défaut lèche vitre	<p>8</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Window</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>Défaut lèche vitre</td></tr> </table>	Part	Window	Position	Front left	Damages	Scratched	Comments	Défaut lèche vitre
Part	Window																		
Position	Back right																		
Damages	Scratched																		
Comments	Défaut lèche vitre																		
Part	Window																		
Position	Front left																		
Damages	Scratched																		
Comments	Défaut lèche vitre																		
<p>9</p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Special rim 17"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 17"	Position	Front right	Damages	Scratched	Comments	-	<p>10</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Special rim 17"</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 17"	Position	Back right	Damages	Scratched	Comments	-
Part	Special rim 17"																		
Position	Front right																		
Damages	Scratched																		
Comments	-																		
Part	Special rim 17"																		
Position	Back right																		
Damages	Scratched																		
Comments	-																		

Comments

Sur tapis repris