


Vehicle details					
VIN	VR7ARHPY7 SL009975	Registration date	10/03/2025	Exterior Color	Platinum Grey
Brand	CITROEN	Licence Plate	2grw049	Odometer	19 758 km
Model	C5 Aircross SUV Hybride 136 e-DCS6 MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Rear parcel shelf	✓
Emergency compressor kit	✗
Refill emergency kit	✗

Technical Document





Service manual holder	✓
User manual	✓
Adapter USB	✓

Tyres







Hankook 225/55/18 V Summer 5.0 mm	Hankook 225/55/18 V Summer 5.0 mm
Michelin 225/55/18 V Summer 5.0 mm	Michelin 225/55/18 V Summer 5.0 mm

Exterior

1		Part	Refill emergency kit	2		Part	Emergency compressor kit
		Position	-			Position	-
		Damages	Missing			Damages	Missing
3		Part	Engine soundproofing	4		Part	Bonnet
		Position	-			Position	-
		Damages	Misaligned			Damages	Misaligned
		Comments	depose\repose			Comments	se ferme pas correctement

DEKRA Automotive Solutions

<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Spoiler</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>renovateur plastique</td></tr> </table>	Part	Spoiler	Position	Front left	Damages	Scratched	Comments	renovateur plastique	<p>6</p>  <p>● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Special rim 18"</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 18"	Position	Back left	Damages	Scratched	Comments	-
Part	Spoiler																		
Position	Front left																		
Damages	Scratched																		
Comments	renovateur plastique																		
Part	Special rim 18"																		
Position	Back left																		
Damages	Scratched																		
Comments	-																		
<p>7</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Special rim 18"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 18"	Position	Front right	Damages	Scratched	Comments	-	<p>8</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Glass weatherstrip</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Glass weatherstrip	Position	Back left	Damages	Dented	Comments	-
Part	Special rim 18"																		
Position	Front right																		
Damages	Scratched																		
Comments	-																		
Part	Glass weatherstrip																		
Position	Back left																		
Damages	Dented																		
Comments	-																		

Comments

Parc stockage : PCD - Hödlmayr Saint-Trond