


DEKRA Automotive Solutions

Vehicle details

VIN	VR7ARHPY8 SL016966	Registration date	15/04/2025	Exterior Color	Eclipse Blue
Brand	CITROEN	Licence Plate		Odometer	15 657 km
Model	C5 Aircross Hybrid 145 ch Automatic MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details


Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Rear parcel shelf	✗



Technical Document





Tyres



Exterior

2		Part	Wing	4		Part	Bumper
		Position	Back left			Position	Front
		Damages	Improper repair			Damages	Scatched
		Comments	afwerking			Comments	-

Interior damage

1		Part	Rear parcel shelf	3		Part	Interior rear-view mirror
		Position	-			Position	Left
		Damages	Missing			Damages	Misaligned
		Comments	-			Comments	(zit los) ovb schade achteraan

Comments

wagen hersteld, slechte afwerking en montage!