


Vehicle details

VIN	VR1URHPY9 SW022684	Registration date	04/04/2025	Exterior Color	Gris Artense
Brand	DS	Licence Plate	N/A	Odometer	26 990 km
Model	DS 3 ETOILE HYBRID	Condition of the car	Unknown	Pre-damage	Unknown
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage	Comments

Inspection Details

Inspection loc.




Removable element

Spare wheel (wheel & tyre)	✓
Triangle	✓
Jack	✓
Safety vest	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Fire extinguisher	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
First aid kit	✓

Tyres





Goodyear 215/55/18 V All seasons 3.0 mm

Goodyear 215/55/18 V All seasons 3.0 mm

Goodyear 215/55/18 V All seasons 5.0 mm

Goodyear 215/55/18 V All seasons 5.0 mm


Exterior

 <p>3</p>	Part	Bumper	 <p>4</p>	Part	Tailgate / Boot door
	Position	Back		Position	-
	Damages	Scatched		Damages	Dented
	Comments	-		Comments	-


DEKRA Automotive Solutions

<b>5</b>		<table border="0"> <tr><td>Part</td><td>Special rim 18"</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 18"	Position	Front left	Damages	Scratched	Comments	-	<b>6</b>		<table border="0"> <tr><td>Part</td><td>Electric door mirror</td></tr> <tr><td>Position</td><td>Left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Electric door mirror	Position	Left	Damages	Scratched	Comments	-
Part	Special rim 18"																				
Position	Front left																				
Damages	Scratched																				
Comments	-																				
Part	Electric door mirror																				
Position	Left																				
Damages	Scratched																				
Comments	-																				

**Interior damage**

<b>2</b>		<table border="0"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Interior tailgate lining	Position	-	Damages	Scratched	Comments	-
Part	Interior tailgate lining									
Position	-									
Damages	Scratched									
Comments	-									

**Others**

<b>1</b>		<table border="0"> <tr><td>Part</td><td>Service</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Service	Position	-	Damages	Missing	Comments	-
Part	Service									
Position	-									
Damages	Missing									
Comments	-									