


DEKRA Automotive Solutions

Vehicle details

VIN	VR3USHPY4 SJ652217	Registration date	13/05/2025	Exterior Color	Selenium Grijs
Brand	PEUGEOT	Licence Plate		Odometer	20 092 km
Model	2008 GT Hybrid 145ch e-DSC6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

Tyres











Goodyear 215/60/17 H All seasons 6.0 mm

Goodyear 215/60/17 H All seasons 6.0 mm



Goodyear 215/60/17 H All seasons 7.0 mm

Goodyear 215/60/17 H All seasons 7.0 mm


Exterior

2		Part	Special rim 17"	3		Part	Engine soundproofing
		Position	Front left			Position	-
4		Damages	Scratched	5		Damages	Cut
		Comments	-			Comments	-
4		Part	Wing extension moulding	5		Part	Unpainted bumper
		Position	Back left			Position	Back
5		Damages	Stained/dirty	5		Damages	Stained/dirty
		Comments	-			Comments	-

DEKRA Automotive Solutions

6		<table border="0"> <tr><td>Part</td><td>Exterior door mirror shell</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Exterior door mirror shell	Position	Front left	Damages	Stone impact	Comments	-	7		<table border="0"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>Centre</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>x2</td></tr> </table>	Part	Roof	Position	Centre	Damages	Dented	Comments	x2
Part	Exterior door mirror shell																				
Position	Front left																				
Damages	Stone impact																				
Comments	-																				
Part	Roof																				
Position	Centre																				
Damages	Dented																				
Comments	x2																				

Interior damage

1		<table border="0"> <tr><td>Part</td><td>Interior complete</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>-</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Interior complete	Position	-	Damages	-	Comments	-
Part	Interior complete									
Position	-									
Damages	-									
Comments	-									

Comments

Parc stockage : OV - Hödlmayr Saint-Trond