


Vehicle details

| | | | | | |
|------------|---|-----------------------------|------------|---------------------|---------------|
| VIN | VR7ARHPY3 SL017068 | Registration date | 15/04/2025 | Exterior Color | Okenite White |
| Brand | CITROEN | Licence Plate | | Odometer | 20 934 km |
| Model | C5 Aircross Hybrid 145 ch Automatic MAX | Condition of the car | Unknown | | |
| Pre-damage | Unknown | Pre-damage amount excl. VAT | - | Pre-damage Comments | |

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

| | |
|-------------------|---|
| Spare wheel kit | ✓ |
| Rear parcel shelf | ✓ |

Technical Document

| | |
|--|--|
| | |
|--|--|

Tyres











Michelin 225/55/18 V Summer 6.0 mm

Michelin 225/55/18 V Summer 6.0 mm

Michelin 225/55/18 V Summer 6.0 mm

Michelin 225/55/18 V Summer 6.0 mm

Exterior

| | | | | | | | |
|---|---|----------|-----------------|---|--|----------|-----------------|
| 1 |  | Part | Special rim 18" | 2 |  | Part | Special rim 18" |
| | | Position | Front left | | | Position | Front right |
| 3 |  | Damages | Scratched | 4 |  | Damages | Scratched |
| | | Comments | - | | | Comments | - |
| 3 |  | Part | Door | 4 |  | Part | Door sill |
| | | Position | Front right | | | Position | Front left |
| 4 |  | Damages | Dented | 4 |  | Damages | Dent & Chips |
| | | Comments | - | | | Comments | - |

Comments

Parc stockage : FCA - Hödlmayr Saint-Trond