

Vehicle details

| | | | | | |
|------------|---|-----------------------------|------------|---------------------|----------------------|
| VIN | VR7CGHPY1 ST177416 | Registration date | 25/09/2025 | Exterior Color | Perla Nera Black (pa |
| Brand | CITROEN | Licence Plate | 00xx00 | Odometer | 21 864 km |
| Model | New C3 Aircross Hybrid 145 ch Automatic MAX | Condition of the car | Unknown | | |
| Pre-damage | Unknown | Pre-damage amount excl. VAT | - | Pre-damage Comments | |

Inspection Details

| | | | |
|-----------------|----------------------------|--|--|
| Inspection loc. | PCD - Hödlmayr Saint-Trond | | |
|-----------------|----------------------------|--|--|


Removable element

| | |
|--------------------------|---|
| Emergency compressor kit | ✘ |
| Refill emergency kit | ✘ |

Technical Document

| | |
|--|--|
| | |
|--|--|

Tyres



Bridgestone 215/60/17 H Summer 5.0 mm
 Bridgestone 215/60/17 H Summer 5.0 mm
 Bridgestone 215/60/17 H Summer 6.0 mm
 Bridgestone 215/60/17 H Summer 6.0 mm

Exterior

| | | | | | |
|---|----------|-------------|---|----------|--------------|
| 1 | Part | Door sill | 2 | Part | Door sill |
| | Position | Front right | | Position | Back right |
| | Damages | Scratched | | Damages | Dent & Chips |
| | Comments | - | | Comments | - |
| 3 | Part | Door | 5 | Part | Door sill |
| | Position | Front right | | Position | Back left |
| | Damages | Dented | | Damages | Dent & Chips |
| | Comments | x2 | | Comments | - |

DEKRA Automotive Solutions

| | | | | | |
|----------|----------|----------------------|----------|----------|--------------------------|
| 7 | Part | Bumper | 8 | Part | Emergency compressor kit |
| | Position | Front | | Position | - |
| | Damages | Scratched | | Damages | Missing |
| | Comments | - | | Comments | - |
| 9 | Part | Refill emergency kit | | | |
| | Position | - | | | |
| | Damages | Missing | | | |
| | Comments | - | | | |

Interior damage

| | | | |
|----------|----------|--------------------------|--|
| 4 | Part | Carpet | |
| | Position | Front left | |
| | Damages | Burnt | |
| | Comments | - | |
| 6 | Part | Interior tailgate lining | |
| | Position | - | |
| | Damages | Scratched | |
| | Comments | - | |