

DEKRA Automotive Solutions

Vehicle details

VIN	VR1FRHPY2 S1022967	Registration date	30/05/2025	Exterior Color	Noir Perla Nera
Brand	DS	Licence Plate	2hcg063	Odometer	19 281 km
Model	DS 4 ETOILE CUIR NAPPA HYBRID	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond		
-----------------	----------------------------	--	--

Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Rear parcel shelf	✓

Technical Document

Service manual holder	✓
User manual	✓
Adapter USB	✓

Tyres



Michelin 205/55/19 V Summer 5.0 mm

Michelin 205/55/19 V Summer 5.0 mm

Michelin 205/55/19 V Summer 5.0 mm

Michelin 205/55/19 V Summer 5.0 mm

Exterior

1	Part	Bonnet	2	Part	Engine soundproofing
	Position	-		Position	-
	Damages	Scratched		Damages	Perforated
	Comments	-		Comments	-
3	Part	Door	4	Part	Wing
	Position	Front left		Position	Back right
	Damages	Scratched		Damages	Dent & Chips
	Comments	-		Comments	-

DEKRA Automotive Solutions

5	● ●	Part	Door	6	● ●	Part	Special rim 19"
		Position	Back right			Position	Front left
		Damages	Dent & Chips			Damages	Scratched
		Comments	-			Comments	-
7	● ● ●	Part	Bumper				
		Position	Front right				
		Damages	Scratched				
		Comments	-				