

Vehicle details

VIN	VR3USHPY9 SJ646719	Registration date	08/05/2025	Exterior Color	Selenium Grijs
Brand	PEUGEOT	Licence Plate		Odometer	22 106 km
Model	2008 GT Hybrid 145ch e-DSC6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Triangle	✓
Safety vest	✓
Fire extinguisher	✓

Technical Document

Service manual holder	✓
User manual	✓
First aid kit	✓

Tyres











Goodyear 215/60/17 H All seasons 5.0 mm

Goodyear 215/60/17 H All seasons 5.0 mm



Goodyear 215/60/17 H All seasons 6.0 mm

Goodyear 215/60/17 H All seasons 6.0 mm


Exterior

3		Part	Door sill	4		Part	Engine soundproofing
		Position	Back right			Position	-
5		Damages	Dent & Chips	6		Damages	Cut
		Comments	-			Comments	-
5		Part	Bonnet	6		Part	Door moulding
		Position	-			Position	Front left
6		Damages	Dented	6		Damages	Scratched
		Comments	-			Comments	-


DEKRA Automotive Solutions

7		Part	Door sill	8		Part	Bumper moulding
		Position	Back left			Position	Back
		Damages	Dent & Chips			Damages	Stone impact
		Comments	-			Comments	-

Interior damage

2		Part	Interior cleaning
		Position	-
		Damages	Not carried out
		Comments	-

Others

1		Part	Service
		Position	-
		Damages	Missing
		Comments	-