

Vehicle details

VIN	VR3UPHNE5 S4089221	Registration date	05/05/2025	Exterior Color	Gris Artense
Brand	PEUGEOT	Licence Plate	2gxm584	Odometer	21 538 km
Model	208 Allure 1.2 Turbo100 Man.6	Condition of the car	Unknown	Pre-damage	Unknown
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond
-----------------	----------------------------



Removable element


Emergency compressor kit	✓
Refill emergency kit	✓
Rear parcel shelf	✓

Technical Document

Service manual holder	✓
User manual	✓
Adapter USB	✓

Tyres

Michelin 195/55/16 V Summer 5.0 mm






Michelin 195/55/16 V Summer 5.0 mm

Michelin 195/55/16 V Summer 5.0 mm



Michelin 195/55/16 V Summer 5.0 mm

Exterior


4		Part	LED daytime driving light	5		Part	Bumper
		Position	Front left			Position	Front left
		Damages	Misaligned			Damages	Scratched
		Comments	sous reserve de demontage			Comments	sous reserve smart
6		Part	Special rim 16"				
		Position	Front right				
		Damages	Scratched				
		Comments	-				

Interior damage

DEKRA Automotive Solutions

1		Part	Interior boot lining
		Position	Back left
2		Damages	Broken
		Comments	-
		Part	Rear parcel shelf retaining strap hook
		Position	Side
		Damages	Missing
		Comments	-

Others

3		Part	Enjoliveur de régulateur de distance
		Position	Front
		Damages	Missing
		Comments	-

Comments

Parc stockage : PCD - Hödlmayr Saint-Trond