


Vehicle details					
VIN	VR3UPHNE7 S4008736	Registration date	21/01/2025	Exterior Color	Noir Perla Nera
Brand	PEUGEOT	Licence Plate	1AOC270	Odometer	19 856 km
Model	208 Allure 1.2 Turbo100 Man.6	Condition of the car	Not repaired after accident	Pre-damage	Comments
Pre-damage	Unknown	Pre-damage amount excl. VAT	-		

Inspection Details

Inspection loc. PCD - Parc LLD



Removable element	
Emergency compressor kit	✓
Refill emergency kit	✓
In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Towing hook	✓





Technical Document	
Service manual holder	✓
User manual	✓
Warranty booklet	✓
Log books	✓
Adapter USB	✓
Spare key	✓
Card Key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres



Michelin 195/55/16 H Summer 5.0 mm
 Michelin 195/55/16 H Summer 5.0 mm
 Michelin 195/55/16 H Summer 6.0 mm
 Michelin 195/55/16 H Summer 6.0 mm

Exterior

1		Part	Bonnet	2		Part	Windscreen with camera
		Position	-			Position	-
3		Damages	Stone impact	4		Damages	Scratched
		Comments	-			Comments	Causée par essuie vitre de mauvaise qualité
		Part	Door			Part	Sill
		Position	Front right			Position	Right
		Damages	Scratched			Damages	Dented
		Comments	-			Comments	-

