

DEKRA Automotive Solutions

Vehicle details

VIN	VR7CGHPV8 ST069168	Registration date	19/05/2025	Exterior Color	Mercury Grey (metall)
Brand	CITROEN	Licence Plate		Odometer	24 712 km
Model	New C3 Aircross Turbo 100 ch Manual PLUS	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Rear parcel shelf	✓
Spare wheel kit	✗

Technical Document






Tyres





Bridgestone 215/60/17 H Summer 5.0 mm
 Bridgestone 215/60/17 H Summer 5.0 mm
 Bridgestone 215/60/17 H Summer 7.0 mm
 Bridgestone 215/60/17 H Summer 7.0 mm

Exterior


2		Part	Spare wheel kit	3		Part	Unpainted bumper
		Position	-			Position	Back
4		Damages	Missing			Damages	Dented
		Comments	-			Comments	-
		Part	Bumper moulding				
		Position	Back left				
		Damages	Dented				
		Comments	-				

Interior damage

DEKRA Automotive Solutions

<p>1</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Fabric seat</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Fabric seat	Position	Front right	Damages	Stained/dirty	Comments	-
Part	Fabric seat								
Position	Front right								
Damages	Stained/dirty								
Comments	-								
<p>6</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Fabric seat</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Fabric seat	Position	Back	Damages	Stained/dirty	Comments	-
Part	Fabric seat								
Position	Back								
Damages	Stained/dirty								
Comments	-								

Others

<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Wiper blade cover</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wiper blade cover	Position	-	Damages	Missing	Comments	-
Part	Wiper blade cover								
Position	-								
Damages	Missing								
Comments	-								