

Vehicle details

VIN	VR7ACYHZ4 SL027519	Registration date	18/06/2025	Exterior Color	Eclipse Blue
Brand	CITROEN	Licence Plate	1LUA413	Odometer	15 256 km
Model	C5 Aircross Diesel 130 ch Automatic MAX	Condition of the car	Condition of use		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓
Adjustable Boot Space	✓



Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Adapter USB	✓
Spare key	✓
Card Key	✓
Certificate of conformity	✓
Title / License document	✓



Tyres




Exterior

1		Part	Unpainted bumper	3		Part	Electric door mirror
		Position	Back			Position	Right
		Damages	Scratched			Damages	Scratched
		Comments	Superficiel			Comments	-

DEKRA Automotive Solutions

4		<table border="0"> <tr><td>Part</td><td>Turning signal side</td></tr> <tr><td>Position</td><td>Right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Turning signal side	Position	Right	Damages	Scratched	Comments	-	5		<table border="0"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Wing	Position	Back right	Damages	Dented	Comments	-
Part	Turning signal side																				
Position	Right																				
Damages	Scratched																				
Comments	-																				
Part	Wing																				
Position	Back right																				
Damages	Dented																				
Comments	-																				

Interior damage

2		<table border="0"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Not carried out</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Interior cleaning	Position	-	Damages	Not carried out	Comments	-
Part	Interior cleaning									
Position	-									
Damages	Not carried out									
Comments	-									