


Vehicle details

| | | | | | |
|------------|---|-----------------------------|------------|---------------------|-----------------------|
| VIN | VR7CGHPY7 ST077949 | Registration date | 02/06/2025 | Exterior Color | Montana Green (metal) |
| Brand | CITROEN | Licence Plate | 2hch332 | Odometer | 19 455 km |
| Model | New C3 Aircross Hybrid 145 ch Automatic MAX | Condition of the car | Unknown | | |
| Pre-damage | Unknown | Pre-damage amount excl. VAT | - | Pre-damage Comments | |

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

| | |
|--------------------------|---|
| Rear parcel shelf | ✓ |
| Emergency compressor kit | ✗ |
| Refill emergency kit | ✗ |

Technical Document

| | |
|-----------------------|---|
| Adapter USB | ✓ |
| Service manual holder | ✗ |
| User manual | ✗ |

Tyres






Bridgestone 215/60/17 H Summer 5.0 mm

Bridgestone 215/60/17 H Summer 5.0 mm

Bridgestone 215/60/17 H Summer 5.0 mm



Bridgestone 215/60/17 H Summer 5.0 mm

Exterior

| | | | | | | | |
|---|---|----------|--------------------------|---|--|----------|----------------------|
| 3 |  | Part | Emergency compressor kit | 4 |  | Part | Refill emergency kit |
| | | Position | - | | | Position | - |
| | | Damages | Missing | | | Damages | Missing |
| | | Comments | - | | | Comments | - |
| 5 |  | Part | Bonnet | | | Part | |
| | | Position | - | | | Position | - |
| | | Damages | Dented | | | Damages | - |
| | | Comments | - | | | Comments | - |

Interior damage

DEKRA Automotive Solutions

| | | | | | | | | | | |
|-----------------|--|--|------|-----------------------|----------|---|---------|---------|----------|---|
| <p>1</p> |  <p style="text-align: center;">●</p> | <table border="1"> <tr> <td>Part</td> <td>Service manual holder</td> </tr> <tr> <td>Position</td> <td>-</td> </tr> <tr> <td>Damages</td> <td>Missing</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </table> | Part | Service manual holder | Position | - | Damages | Missing | Comments | - |
| Part | Service manual holder | | | | | | | | | |
| Position | - | | | | | | | | | |
| Damages | Missing | | | | | | | | | |
| Comments | - | | | | | | | | | |
| <p>2</p> |  <p style="text-align: center;">●</p> | <table border="1"> <tr> <td>Part</td> <td>User manual</td> </tr> <tr> <td>Position</td> <td>-</td> </tr> <tr> <td>Damages</td> <td>Missing</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </table> | Part | User manual | Position | - | Damages | Missing | Comments | - |
| Part | User manual | | | | | | | | | |
| Position | - | | | | | | | | | |
| Damages | Missing | | | | | | | | | |
| Comments | - | | | | | | | | | |