


### Vehicle details

VIN	VR3USHPY8 SJ653581	Registration date	13/05/2025	Exterior Color	Perla Nera Zwart
Brand	PEUGEOT	Licence Plate		Odometer	22 140 km
Model	2008 GT Hybrid 145ch e-DSC6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

### Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




### Removable element

Rear parcel shelf ✘

### Technical Document

### Tyres







Goodyear 215/60/17 H All seasons 5.0 mm

Goodyear 215/60/17 H All seasons 5.0 mm




Goodyear 215/60/17 H All seasons 5.0 mm

Goodyear 215/60/17 H All seasons 5.0 mm


### Exterior

2		Part	Bonnet	3		Part	Bumper
		Position	Front			Position	Front
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-
4		Part	Wing	5		Part	Door
		Position	Front left			Position	Front left
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-

DEKRA Automotive Solutions

<p>6</p>		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Back left	Damages	Scratched	Comments	-	<p>7</p>		<table border="1"> <tr><td>Part</td><td>Bumper moulding</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper moulding	Position	Back	Damages	Scratched	Comments	-
Part	Bumper																				
Position	Back left																				
Damages	Scratched																				
Comments	-																				
Part	Bumper moulding																				
Position	Back																				
Damages	Scratched																				
Comments	-																				
<p>8</p>		<table border="1"> <tr><td>Part</td><td>Tailgate / Boot door</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Tailgate / Boot door	Position	Back	Damages	Scratched	Comments	-											
Part	Tailgate / Boot door																				
Position	Back																				
Damages	Scratched																				
Comments	-																				

Interior damage

<p>1</p>		<table border="1"> <tr><td>Part</td><td>Rear parcel shelf</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Rear parcel shelf	Position	-	Damages	Missing	Comments	-
Part	Rear parcel shelf									
Position	-									
Damages	Missing									
Comments	-									