

Vehicle details

| | | | | | |
|------------|------------------------------|-----------------------------|------------|---------------------|------------------|
| VIN | VR3UPPHY6 S4173605 | Registration date | 18/08/2025 | Exterior Color | Zwart Perla Nera |
| Brand | PEUGEOT | Licence Plate | N/A | Odometer | 20 643 km |
| Model | 208 GT 1.2 Hybrid 145 e-DCS6 | Condition of the car | Unknown | | |
| Pre-damage | Unknown | Pre-damage amount excl. VAT | - | Pre-damage Comments | |

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

| | |
|----------------------------|---|
| Spare wheel (wheel & tyre) | ✓ |
| Rear parcel shelf | ✓ |

Technical Document

Tyres







Michelin 205/45/17 V Summer 5.0 mm

Michelin 205/45/17 V Summer 5.0 mm




Michelin 205/45/17 V Summer 6.0 mm

Michelin 205/45/17 V Summer 6.0 mm



Exterior

| | | | | | | | |
|---|---|----------|-----------------|---|--|----------|-------------------------|
| 1 |  | Part | Bumper | 2 |  | Part | Wing extension moulding |
| | | Position | Front | | | Position | Front right |
| | | Damages | Scratched | | | Damages | Scratched |
| | | Comments | - | | | Comments | - |
| 3 |  | Part | Special rim 17" | 5 |  | Part | Special rim 17" |
| | | Position | Front right | | | Position | Back right |
| | | Damages | Scratched | | | Damages | Scratched |
| | | Comments | - | | | Comments | - |

DEKRA Automotive Solutions

| | | | | | | | | | | | | | | | | | | | | | |
|----------|--|--|------|--------|----------|-------|---------|--------|----------|---|---|---|---|------|------|----------|--------|---------|--------|----------|---|
| 7 |  <p>● ●</p> | <table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table> | Part | Bumper | Position | Back | Damages | Dented | Comments | - | 8 |  <p>● ●</p> | <table border="1"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>Centre</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table> | Part | Roof | Position | Centre | Damages | Dented | Comments | - |
| Part | Bumper | | | | | | | | | | | | | | | | | | | | |
| Position | Back | | | | | | | | | | | | | | | | | | | | |
| Damages | Dented | | | | | | | | | | | | | | | | | | | | |
| Comments | - | | | | | | | | | | | | | | | | | | | | |
| Part | Roof | | | | | | | | | | | | | | | | | | | | |
| Position | Centre | | | | | | | | | | | | | | | | | | | | |
| Damages | Dented | | | | | | | | | | | | | | | | | | | | |
| Comments | - | | | | | | | | | | | | | | | | | | | | |
| 9 |  <p>● ● ●</p> | <table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table> | Part | Bonnet | Position | Front | Damages | Dented | Comments | - | | | | | | | | | | | |
| Part | Bonnet | | | | | | | | | | | | | | | | | | | | |
| Position | Front | | | | | | | | | | | | | | | | | | | | |
| Damages | Dented | | | | | | | | | | | | | | | | | | | | |
| Comments | - | | | | | | | | | | | | | | | | | | | | |

Interior damage

| | | | | | | | | | | | | | |
|----------|--|--|------|--|----------|------------|---------|-----------------|----------|---|--|--|--|
| 4 |  <p>● ● ● ● ●</p> | <table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Not carried out</td></tr> <tr><td>Comments</td><td>-</td></tr> </table> | Part | Interior cleaning | Position | - | Damages | Not carried out | Comments | - | | | |
| Part | Interior cleaning | | | | | | | | | | | | |
| Position | - | | | | | | | | | | | | |
| Damages | Not carried out | | | | | | | | | | | | |
| Comments | - | | | | | | | | | | | | |
| 6 |  <p>● ●</p> | <table border="1"> <tr><td>Part</td><td>Rear parcel shelf retaining strap hook</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table> | Part | Rear parcel shelf retaining strap hook | Position | Back right | Damages | Missing | Comments | - | | | |
| Part | Rear parcel shelf retaining strap hook | | | | | | | | | | | | |
| Position | Back right | | | | | | | | | | | | |
| Damages | Missing | | | | | | | | | | | | |
| Comments | - | | | | | | | | | | | | |