


Vehicle details

|            |   |                             |            |                     |                      |
|------------|---|-----------------------------|------------|---------------------|----------------------|
| VIN        | VR7CGHPY7 ST120105                          | Registration date           | 01/08/2025 | Exterior Color      | Perla Nera Black (pa |
| Brand      | CITROEN                                     | Licence Plate               |            | Odometer            | 13 878 km            |
| Model      | New C3 Aircross Hybrid 145 ch Automatic MAX | Condition of the car        | Unknown    |                     |                      |
| Pre-damage | Unknown                                     | Pre-damage amount excl. VAT | -          | Pre-damage Comments |                      |

Inspection Details




Removable element

|                          |   |
|--------------------------|---|
| Triangle                 | ✓ |
| Safety vest              | ✓ |
| Fire extinguisher        | ✓ |
| Emergency compressor kit | ✗ |
| Refill emergency kit     | ✗ |





Technical Document

|                       |   |
|-----------------------|---|
| Service manual holder | ✓ |
| User manual           | ✓ |
| First aid kit         | ✓ |






Tyres



Exterior

|   |   |          |                          |   |  |          |                      |
|---|---|----------|--------------------------|---|--|----------|----------------------|
| 1 |  | Part     | Emergency compressor kit | 2 |  | Part     | Refill emergency kit |
|   |   | Position | -                        |   |  | Position | -                    |
|   |   | Damages  | Missing                  |   |  | Damages  | Missing              |
| 3 |  | Part     | Door                     | 4 |  | Part     | Bumper               |
|   |   | Position | Back left                |   |  | Position | Back                 |
|   |   | Damages  | Dented                   |   |  | Damages  | Scratched            |
|   |   | Comments | -                        |   |  | Comments | -                    |

DEKRA Automotive Solutions

|   |   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
|---|---|------|----------------------------|----------|-------------|---------|--------------|----------|---|--|--|------|-----------------|----------|------------|---------|--------------|----------|---|
| <p>5</p>  <p>● ● ●</p> | <table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dent &amp; Chips</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>           | Part | Door                       | Position | Back right  | Damages | Dent & Chips | Comments | - | <p>6</p>  <p>● ● ●</p> | <table border="1"> <tr><td>Part</td><td>Door sill</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dent &amp; Chips</td></tr> <tr><td>Comments</td><td>-</td></tr> </table> | Part | Door sill       | Position | Back right | Damages | Dent & Chips | Comments | - |
| Part  | Door  |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Position  | Back right  |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Damages   | Dent & Chips  |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Comments  | -   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Part  | Door sill   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Position  | Back right  |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Damages   | Dent & Chips  |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Comments  | -   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| <p>7</p>  <p>● ●</p>   | <table border="1"> <tr><td>Part</td><td>Exterior door mirror shell</td></tr> <tr><td>Position</td><td>Right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table> | Part | Exterior door mirror shell | Position | Right       | Damages | Scratched    | Comments | - | <p>8</p>  <p>● ● ●</p> | <table border="1"> <tr><td>Part</td><td>Bumper moulding</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>       | Part | Bumper moulding | Position | Front      | Damages | Scratched    | Comments | - |
| Part  | Exterior door mirror shell  |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Position  | Right   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Damages   | Scratched   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Comments  | -   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Part  | Bumper moulding   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Position  | Front   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Damages   | Scratched   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Comments  | -   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| <p>9</p>  <p>● ●</p>   | <table border="1"> <tr><td>Part</td><td>Bumper moulding</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>      | Part | Bumper moulding            | Position | Front right | Damages | Scratched    | Comments | - |  |  |      |                 |          |            |         |              |          |   |
| Part  | Bumper moulding   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Position  | Front right   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Damages   | Scratched   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |
| Comments  | -   |      |                            |          |             |         |              |          |   |  |  |      |                 |          |            |         |              |          |   |