

Vehicle details

VIN	VR1JCYHZ5 SY564011	Registration date	01/07/2025	Exterior Color	Noir Perla Nera
Brand	DS	Licence Plate	N/A	Odometer	28 370 km
Model	DS 7 BLUEHDI 130 AUTOMATIC ETOILE	Condition of the car	Compliant		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element





Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document



Tyres



Exterior

1		Part	Door	2		Part	Wing
		Position	Back right			Position	Back right
3		Damages	Dent & Chips	4		Damages	Dented
		Comments	-			Comments	-
		Part	Bumper			Part	Wing
		Position	Back			Position	Back left
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-

DEKRA Automotive Solutions

5		<table border="0"> <tr> <td>Part</td> <td>Door</td> </tr> <tr> <td>Position</td> <td>Front right</td> </tr> <tr> <td>Damages</td> <td>Scratched</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </table>	Part	Door	Position	Front right	Damages	Scratched	Comments	-	6		<table border="0"> <tr> <td>Part</td> <td>Tailgate / Boot door</td> </tr> <tr> <td>Position</td> <td>Back</td> </tr> <tr> <td>Damages</td> <td>Dent & Chips</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </table>	Part	Tailgate / Boot door	Position	Back	Damages	Dent & Chips	Comments	-
Part	Door																				
Position	Front right																				
Damages	Scratched																				
Comments	-																				
Part	Tailgate / Boot door																				
Position	Back																				
Damages	Dent & Chips																				
Comments	-																				

Comments

Parc stockage : FCA - Hödlmayr Saint-Trond