

Vehicle details

VIN	VR7ACYHZ0 SL008031	Registration date	28/03/2025	Exterior Color	Perla Nera Black
Brand	CITROEN	Licence Plate	2gua541	Odometer	10 069 km
Model	C5 Aircross Diesel 130 ch Automatic MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Rear parcel shelf	✓
Emergency compressor kit	✗
Refill emergency kit	✗





Technical Document

Service manual holder	✓
User manual	✓
Adapter USB	✓
Spare key	✓

Tyres




Exterior


1		Part	Refill emergency kit	2		Part	Emergency compressor kit
		Position	-			Position	-
		Damages	Missing			Damages	Missing
		Comments	-			Comments	-
3		Part	Roof	6		Part	Bonnet
		Position	-			Position	-
		Damages	Chemical deposit			Damages	Dented
		Comments	-			Comments	-

Interior damage

DEKRA Automotive Solutions

<b>5</b>		Part	Interior cleaning
		Position	-
		Damages	Not carried out
		Comments	-
		● ● ●	

Others

<b>4</b>		Part	Service
		Position	-
		Damages	Missing
		Comments	-
		●	