

Vehicle details

VIN	VR1FRHPY0 S1027357	Registration date	18/06/2025	Exterior Color	Gris Platinum
Brand	DS	Licence Plate	00xx00	Odometer	19 856 km
Model	DS 4 ETOILE ALCANTARA@HYBRID	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details


Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document



Tyres

Michelin 205/55/19 V Summer 6.0 mm











Michelin 205/55/19 V Summer 6.0 mm

Michelin 205/55/19 V Summer 6.0 mm

Michelin 205/55/19 V Summer 6.0 mm




Exterior

4		Part	Bonnet	5		Part	Special rim 19"
		Position	Front			Position	Front right
6		Damages	Chemical deposit	7		Damages	Scratched
		Comments	-			Comments	-
6		Part	Door	7		Position	Bumper
		Position	Back left			Position	Back
7		Damages	Dented	7		Damages	Scratched
		Comments	-			Comments	-

Interior damage



DEKRA Automotive Solutions

<p>1</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>A-pillar trim</td> </tr> <tr> <td>Position</td> <td>Front left</td> </tr> <tr> <td>Damages</td> <td>Burnt</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </tbody> </table>	Part	A-pillar trim	Position	Front left	Damages	Burnt	Comments	-	<p>2</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Fabric seat</td> </tr> <tr> <td>Position</td> <td>Front left</td> </tr> <tr> <td>Damages</td> <td>Burnt</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </tbody> </table>	Part	Fabric seat	Position	Front left	Damages	Burnt	Comments	-
Part	A-pillar trim																		
Position	Front left																		
Damages	Burnt																		
Comments	-																		
Part	Fabric seat																		
Position	Front left																		
Damages	Burnt																		
Comments	-																		
<p>3</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Carpet</td> </tr> <tr> <td>Position</td> <td>Front left</td> </tr> <tr> <td>Damages</td> <td>Burnt</td> </tr> <tr> <td>Comments</td> <td>-</td> </tr> </tbody> </table>	Part	Carpet	Position	Front left	Damages	Burnt	Comments	-										
Part	Carpet																		
Position	Front left																		
Damages	Burnt																		
Comments	-																		