

Vehicle details

VIN	VR3UPHNE7 S4142002	Registration date	08/08/2025	Exterior Color	Selenium Grijs
Brand	PEUGEOT	Licence Plate	N/A	Odometer	8 522 km
Model	208 Allure 1.2 Turbo 100ch Man.6	Condition of the car	Condition of use		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓
Adjustable Boot Space	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Adapter USB	✓
Spare key	✓
Card Key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres




Exterior

1		Part	Bonnet	2		Part	Bumper
		Position	-			Position	Back
		Damages	Stone impact			Damages	Scratched
		Comments	-			Comments	-

DEKRA Automotive Solutions

4		Part	Door
		Position	Front right
		Damages	Stone impact
		Comments	-
			
5		Part	Door sill
		Position	Front right
		Damages	Dented
		Comments	-
			
6		Part	Roof
		Position	-
		Damages	Dented
		Comments	-
			
7		Part	Door
		Position	Back right
		Damages	Dented
		Comments	-
			

Interior damage

3		Part	Interior cleaning
		Position	-
		Damages	Not carried out
		Comments	-
			