

Vehicle details

VIN	VR3KAHPY5 SS094754	Registration date	17/06/2025	Exterior Color	Bleu Ingaro
Brand	PEUGEOT	Licence Plate		Odometer	16 130 km
Model	New 3008 Allure Hybrid 145 e-DCS6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Rear parcel shelf	✗

Technical Document

Service manual holder	✓
User manual	✓

Tyres

Michelin 225/55/19 V Summer 6.0 mm



Michelin 225/55/19 V Summer 6.0 mm



Michelin 225/55/19 V Summer 7.0 mm



Michelin 225/55/19 V Summer 7.0 mm

Exterior

2



Part	Tailgate / Boot door
Position	-
Damages	Stone impact
Comments	-

3



Part	Bumper moulding
Position	Back
Damages	Stone impact
Comments	-

5



Part	Special rim 19"
Position	Front left
Damages	Scratched
Comments	-

6



Part	Door
Position	Front left
Damages	Dent & Chips
Comments	-

7



Part	Special rim 19"
Position	Back left
Damages	Scratched
Comments	-

8



Part	Wing extension moulding
Position	Back right
Damages	Scratched
Comments	-

9



Part	Special rim 19"
Position	Front right
Damages	Scratched
Comments	-

10



Part	Special rim 19"
Position	Back right
Damages	Scratched
Comments	-

Interior damage

1



●

Part	Rear parcel shelf
Position	-
Damages	Missing
Comments	-

4



● ● ●

Part	Interior cleaning
Position	-
Damages	Not carried out
Comments	-