

## Vehicle details

|            |                               |                             |            |                     |             |
|------------|-------------------------------|-----------------------------|------------|---------------------|-------------|
| VIN        | VR3USHPY4 SJ851994            | Registration date           | 20/10/2025 | Exterior Color      | Artens Gris |
| Brand      | PEUGEOT                       | Licence Plate               |            | Odometer            | 11 916 km   |
| Model      | 2008 Allure Hybrid 145 e-DSC6 | Condition of the car        | Unknown    |                     |             |
| Pre-damage | Unknown                       | Pre-damage amount excl. VAT | -          | Pre-damage Comments |             |

## Inspection Details

Inspection loc. PCD - Parc LLD




## Removable element

|                          |   |
|--------------------------|---|
| Rear parcel shelf        | ✓ |
| Emergency compressor kit | ✗ |
| Refill emergency kit     | ✗ |

## Technical Document

## Tyres

Goodyear 215/60/17 H All seasons  
6.0 mm

Goodyear 215/60/17 H All seasons  
6.0 mm

Continental 215/60/17 H All seasons  
7.0 mm

Continental 215/60/17 H All seasons  
7.0 mm

## Exterior

|   |                                                                                     |          |                          |   |                                                                                      |          |                      |
|---|-------------------------------------------------------------------------------------|----------|--------------------------|---|--------------------------------------------------------------------------------------|----------|----------------------|
| 1 |  | Part     | Emergency compressor kit | 2 |  | Part     | Refill emergency kit |
|   |                                                                                     | Position | -                        |   |                                                                                      | Position | -                    |
|   |                                                                                     | Damages  | Missing                  |   |                                                                                      | Damages  | Missing              |
|   |                                                                                     | Comments | -                        |   |                                                                                      | Comments | -                    |
| 3 |  | Part     | Exterior door handles    | 4 |  | Part     | Bumper moulding      |
|   |                                                                                     | Position | Front right              |   |                                                                                      | Position | Back                 |
|   |                                                                                     | Damages  | Scratched                |   |                                                                                      | Damages  | Scratched            |
|   |                                                                                     | Comments | smart                    |   |                                                                                      | Comments | polijsten            |

## Comments

Parc stockage : FCA - Hödlmayr Saint-Trond