

Vehicle details

VIN	VR1URHPY8 SW067986	Registration date	02/10/2025	Exterior Color	Gris Artense
Brand	DS	Licence Plate		Odometer	12 201 km
Model	DS 3 ETOILE HYBRID	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element


Spare wheel (wheel & tyre)



Technical Document

Tyres

Goodyear 215/55/18 V Summer 6.0 mm



Goodyear 215/55/18 V Summer 6.0 mm



Goodyear 215/55/18 V Summer 6.0 mm

Goodyear 215/55/18 V Summer 6.0 mm

Exterior

2



Part	Roof
Position	-
Damages	Chemical deposit
Comments	herstellen

3



Part	Bonnet
Position	Front
Damages	Chemical deposit
Comments	polish

4



Part	Door sill
Position	Back right
Damages	Dented
Comments	smart

Others

1		Part	Fuel lumpsum
		Position	-
		Damages	Missing
		Comments	vervangen