DEKRA

DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR3USHPY6 SJ966970	Registration date	14/01/2026	Exterior Color	Selenium Grijs
Brand	PEUGEOT	Licence Plate	00xx00	Odometer	25 352 km
Model	2008 GT 1.2 Hybrid 145 ch e-DCS6	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond















Removable element


Emergency compressor kit	✖
Refill emergency kit	✖

Technical Document

Tyres

Bridgestone 215/60/17 H Summer 6.0 mm

Bridgestone 215/60/17 H Summer 6.0 mm





Bridgestone 215/60/17 H Summer 7.0 mm

Bridgestone 215/60/17 H Summer 7.0 mm

Exterior

1



Part	Engine soundproofing
Position	-
Damages	Cut
Comments	-

2



Part	Emergency compressor kit
Position	-
Damages	Missing
Comments	-

3



Part	Refill emergency kit
Position	-
Damages	Missing
Comments	-

4



Part	Bumper grille
Position	Front
Damages	Broken
Comments	-

5



Part	Bumper moulding
Position	Front
Damages	Stone impact
Comments	-

6



Part	Bumper
Position	Back
Damages	Scratched
Comments	-

7



Part	Wing extension moulding
Position	Back left
Damages	Scratched
Comments	-

8



Part	Roof
Position	-
Damages	Chemical deposit
Comments	ovb