

Vehicle details

VIN	VR7KAHPY3 TL014359	Registration date	09/03/2026	Exterior Color	Platinum Grey (meta
Brand	CITROEN	Licence Plate	00xx00	Odometer	19 649 km
Model	New C5 Aircross Hybrid 145 ch Automatic MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit




Refill emergency kit



Technical Document

Tyres

Michelin 225/55/19 V All seasons 6.0 mm



Michelin 225/55/19 V All seasons 6.0 mm



Michelin 225/55/19 V All seasons 7.0 mm

Michelin 225/55/19 V All seasons 7.0 mm

Exterior

1



Part	Alloy wheel 19"
Position	Front right
Damages	Scratched
Comments	-

2



Part	Door
Position	Front right
Damages	Dented
Comments	ovb resultaat

3



Part	Exterior door handles
Position	Front right
Damages	Scratched
Comments	-

4



Part	Alloy wheel 19"
Position	Back right
Damages	Scratched
Comments	-

5

A close-up photograph of the rear of a dark-colored car, specifically the tailgate area. A hand is holding a green measuring tool against the surface. The car's body shows a small dent and a chip.

Three green dots are placed horizontally, indicating the location of the damage on the tailgate.

Part	Tailgate / Boot door
Position	-
Damages	Dent & Chips
Comments	-

6

A close-up photograph of the rear of a dark-colored car, specifically the tailgate area. A hand is holding a green measuring tool against the surface. The car's body shows a small dent and a chip.

One green dot is placed horizontally, indicating the location of the damage on the tailgate.

Part	Tailgate / Boot door badge
Position	-
Damages	Dent & Chips
Comments	-

7

A close-up photograph of the rear of a dark-colored car, specifically the bumper area. A hand is holding a green measuring tool against the surface. The bumper shows several scratches.

Seven green dots are placed horizontally, indicating the location of the damage on the bumper.

Part	Bumper
Position	Back
Damages	Scratched
Comments	-

8

A close-up photograph of the rear of a dark-colored car, specifically the lower bumper area. A hand is holding a green measuring tool against the surface. The bumper shows several scratches.

Two green dots are placed horizontally, indicating the location of the damage on the lower bumper.

Part	Lower bumper
Position	Back
Damages	Scratched
Comments	-