

Vehicle details

VIN	VR7CGHPY4 ST287408	Registration date	30/01/2026	Exterior Color	Perla Nera Black (pa
Brand	CITROEN	Licence Plate	2JDN718	Odometer	9 621 km
Model	New C3 Aircross Hybrid 145 ch Automatic MAX	Condition of the car	Not repaired after accident		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.




Removable element

In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Towing hook	✓
Adjustable Boot Space	✓
Emergency compressor kit	✗
Refill emergency kit	✗

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Adapter USB	✓
Remote key	✓

Tyres

Goodyear 215/60/17 V All seasons
6.0 mm

Goodyear 215/60/17 V All seasons
6.0 mm

Goodyear 215/60/17 V All seasons
7.0 mm

Goodyear 215/60/17 V All seasons
7.0 mm

Exterior

1		Part	Bumper moulding	2		Part	Bumper extension moulding
		Position	Front right			Position	Front right
		Damages	Scratched			Damages	Scratched
		Comments	-			Comments	-

3		<table><tr><td>Part</td><td>Bumper grille</td></tr><tr><td>Position</td><td>Front</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>Superficiel</td></tr></table>	Part	Bumper grille	Position	Front	Damages	Scratched	Comments	Superficiel	4		<table><tr><td>Part</td><td>Door</td></tr><tr><td>Position</td><td>Front left</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Door	Position	Front left	Damages	Scratched	Comments	-
Part	Bumper grille																				
Position	Front																				
Damages	Scratched																				
Comments	Superficiel																				
Part	Door																				
Position	Front left																				
Damages	Scratched																				
Comments	-																				
5		<table><tr><td>Part</td><td>Roof post A/B/C</td></tr><tr><td>Position</td><td>Back left</td></tr><tr><td>Damages</td><td>Dented</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Roof post A/B/C	Position	Back left	Damages	Dented	Comments	-	6		<table><tr><td>Part</td><td>Special rim 17"</td></tr><tr><td>Position</td><td>Front right</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Special rim 17"	Position	Front right	Damages	Scratched	Comments	-
Part	Roof post A/B/C																				
Position	Back left																				
Damages	Dented																				
Comments	-																				
Part	Special rim 17"																				
Position	Front right																				
Damages	Scratched																				
Comments	-																				
7		<table><tr><td>Part</td><td>Windscreen with camera</td></tr><tr><td>Position</td><td>-</td></tr><tr><td>Damages</td><td>Stone impact</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Windscreen with camera	Position	-	Damages	Stone impact	Comments	-	8		<table><tr><td>Part</td><td>Bonnet</td></tr><tr><td>Position</td><td>-</td></tr><tr><td>Damages</td><td>Dented</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Bonnet	Position	-	Damages	Dented	Comments	-
Part	Windscreen with camera																				
Position	-																				
Damages	Stone impact																				
Comments	-																				
Part	Bonnet																				
Position	-																				
Damages	Dented																				
Comments	-																				
9		<table><tr><td>Part</td><td>Wing</td></tr><tr><td>Position</td><td>Front right</td></tr><tr><td>Damages</td><td>Dented</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Wing	Position	Front right	Damages	Dented	Comments	-	10		<table><tr><td>Part</td><td>Emergency compressor kit</td></tr><tr><td>Position</td><td>-</td></tr><tr><td>Damages</td><td>Missing</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Emergency compressor kit	Position	-	Damages	Missing	Comments	-
Part	Wing																				
Position	Front right																				
Damages	Dented																				
Comments	-																				
Part	Emergency compressor kit																				
Position	-																				
Damages	Missing																				
Comments	-																				
11		<table><tr><td>Part</td><td>Refill emergency kit</td></tr><tr><td>Position</td><td>-</td></tr><tr><td>Damages</td><td>Missing</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Refill emergency kit	Position	-	Damages	Missing	Comments	-	12		<table><tr><td>Part</td><td>Door</td></tr><tr><td>Position</td><td>Back left</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Door	Position	Back left	Damages	Scratched	Comments	-
Part	Refill emergency kit																				
Position	-																				
Damages	Missing																				
Comments	-																				
Part	Door																				
Position	Back left																				
Damages	Scratched																				
Comments	-																				

Comments

Réserve démontage pour choc AV