DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR7CCHPXX TT029804	Registration date	12/02/2026	Exterior Color	Mercury Grey (metall
Brand	CITROEN	Licence Plate		Odometer	15 797 km
Model	C3 Hybrid 110 ch Automatic MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Hödlmayr Saint-Trond















Removable element


Emergency compressor kit	✔
Refill emergency kit	✔
Rear parcel shelf	✖

Technical Document

Tyres

Goodyear 205/50/17 V Summer 5.0 mm

Goodyear 205/50/17 V Summer 5.0 mm



Goodyear 205/50/17 V Summer 6.0 mm

Goodyear 205/50/17 V Summer 6.0 mm

Exterior

2



Part	Rear window tinted
Position	-
Damages	Sticker marked
Comments	-

3




Part	Special rim 17"
Position	Front left
Damages	Scratched
Comments	-

4



Part	Special rim 17"
Position	Front right
Damages	Scratched
Comments	-

5



Part	Tyre
Position	Front right
Damages	Cut
Comments	-

6



Part	Bumper
Position	Front
Damages	Scratched
Comments	-

Interior damage

1



Part	Rear parcel shelf
Position	-
Damages	Missing
Comments	-