

## Vehicle details

|            |                                  |                             |            |                     |             |
|------------|----------------------------------|-----------------------------|------------|---------------------|-------------|
| VIN        | VR3USHPY4 SJ935023               | Registration date           | 08/12/2025 | Exterior Color      | Artens Gris |
| Brand      | PEUGEOT                          | Licence Plate               |            | Odometer            | 19 919 km   |
| Model      | 2008 GT 1.2 Hybrid 145 ch e-DCS6 | Condition of the car        | Unknown    |                     |             |
| Pre-damage | Unknown                          | Pre-damage amount excl. VAT | -          | Pre-damage Comments |             |

## Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond




## Removable element

|                          |   |
|--------------------------|---|
| Rear parcel shelf        | ✓ |
| Emergency compressor kit | ✗ |
| Refill emergency kit     | ✗ |

## Technical Document

## Tyres

Goodyear 215/60/17 H All seasons  
6.0 mm



Goodyear 215/60/17 H All seasons  
6.0 mm



Goodyear 215/60/17 H All seasons  
7.0 mm

Goodyear 215/60/17 H All seasons  
7.0 mm

## Exterior

1



|          |                      |
|----------|----------------------|
| Part     | Tailgate / Boot door |
| Position | Back                 |
| Damages  | Scratched            |
| Comments | -                    |

2



|          |           |
|----------|-----------|
| Part     | Roof      |
| Position | Centre    |
| Damages  | Scratched |
| Comments | -         |

|   |                                                                                   |          |                          |   |                                                                                    |          |                      |
|---|-----------------------------------------------------------------------------------|----------|--------------------------|---|------------------------------------------------------------------------------------|----------|----------------------|
| 3 |  | Part     | Emergency compressor kit | 4 |  | Part     | Refill emergency kit |
|   |                                                                                   | Position | -                        |   |                                                                                    | Position | -                    |
|   |                                                                                   | Damages  | Missing                  |   |                                                                                    | Damages  | Missing              |
|   |                                                                                   | Comments | -                        |   |                                                                                    | Comments | -                    |
|   |                                                                                   |          |                          |   |                                                                                    |          |                      |

Comments

Parc stockage : FCA - Hödlmayr Saint-Trond