DEKRA Automotive Solutions

Appraisal Report

STELLANTIS

Vehicle details

VIN	VR3KAHPYX TS031229	Registration date	01/01/1900	Exterior Color	Unknown
Brand	PEUGEOT	Licence Plate	N/A	Odometer	21 990 km
Model	3008 1.2 HYBRID 145 e-DSC6 Allure	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	Hödlmayr Logistics Belgium N.V.




Removable element

Spare wheel kit	✔
Rear parcel shelf	✔

Technical Document

Tyres



Michelin 225/55/19 V Summer 7.0 mm	Michelin 225/55/19 V Summer 7.0 mm
Michelin 225/55/19 V Summer 7.0 mm	Michelin 225/55/19 V Summer 7.0 mm



Exterior

2



Part	Special rim 19"
Position	Front right
Damages	Scratched
Comments	-

3



Part	Tailgate / Boot door
Position	Back
Damages	Dent & Chips
Comments	-

4



Part	Bumper moulding
Position	Back
Damages	Dented
Comments	-

5



Part	Bumper
Position	Back left
Damages	Scratched
Comments	-

6		Part	Bumper
		Position	Front
		Damages	Dented
		Comments	-

7		Part	Bumper
		Position	Back right
		Damages	Scratched
		Comments	-

Interior damage

1		Part	Seat upholstery mixed
		Position	Front right
		Damages	Burnt
		Comments	-

Comments

Parc stockage : FCA - Hödlmayr Saint-Trond